

10 is the number of plants, but not a good estimate for the total cost. You need to estimate the cost of one plant and multiply by 10.